



# Injector Support and Service

## Common/Frequent Failure items

Prices valid as 12/13/2017

### Stellant Injector

Syringe Size Sensor Kit (new style)	090-101-U	\$ 735.48
Heater "Heat Maintainer" (New Style)	090-109-U	\$ 1,399.57
Motor with encoder. (A or B side)	090-111	\$ 1,495.86
Dual Overlay Assembly	090-113-A	\$ 1,973.49
Switch, Power, Stellant	092-107	\$ 207.63
Green cap, Switch, Power, Stellant	092-108	\$ 21.34
Power Drive Card (Dual/Single)	093-107	\$ 530.77
Head Interface Card (Dual)	093-106	\$ 860.46
48V Power Supply	093-114-1	\$ 530.06
Head Cable, Stellant D	094-101-1	\$ 939.09
Assy, cable, head ext, 75 ft, single/dual	094-105-1	\$ 1,695.08
Dust cover, Switch, Power, Stellant/Solaris	082-115	\$ 22.23

### Solaris Injector

Bottom head cover for EP	080-110	\$ 640.33
Top head cover for EP	080-106	\$ 515.90
Top head cover warning label	080-108	\$ 18.37
Top head check for air label	080-109	\$ 16.30
Solaris Battery Pack (one per order)	081-101-1-A	\$ 454.79
Switch, Power, Solaris	082-114	\$ 165.76
Dust cover, Switch, Power, Stellant/Solaris	082-115	\$ 22.23
Green cap, Switch, Power, Solaris	082-116	\$ 21.35
Solaris Syringe Interface (A)	083-101	\$ 461.54
Solaris Syringe Interface (B)	083-102	\$ 461.54
Head interconnect PCB	083-109	\$ 937.13
Fiber Optic Cable, 125'	084-102-1-125	\$ 1,050.00
Battery Back plate	081-108	\$ 74.16
Gasket, Solaris, EMI	081-109	\$ 322.22
Cable, Solaris, Start	094-113	\$ 348.36

### Envision Service Parts Kit

Knuckle, Envision, Kit	060-116-A	\$ 153.72
Syringe Size Sensor	060-108	\$ 468.77
Cover, Envision, Head Top	060-124	\$ 85.16
Keyboard, Envision, Head	060-125	\$ 583.20
Overlay, Envision, Head	060-126	\$ 76.12
Cover, Envision, Head, Bottom	060-127	\$ 221.20
Strain Relief, Envision, Head cable	060-128	\$ 8.25
Touch Screen, Envision	062-101-2	\$ 492.71
LCD, Envision	062-105-1	\$ 803.50
Cable, Envision, Head, 6'	064-101	\$ 1,058.20

\* Prices are subject to change without notice



# Injector Support and Service

## Common/Frequent Failure items

### Provis Injector

Head cover, Top, Provis	050-123	\$	484.01
Head cover, Bottom, Provis	050-124	\$	484.01
M.S. MOTOR - ISS Assembly	050-133-1-A	\$	284.41
Heater, Provis	050-149	\$	1,232.76
PSI Jacket Lock Lever kit	050-173	\$	79.35
150/200ML Provis Overlay	050-206	\$	755.39
Remote overlay for Provis	052-204	\$	400.51
MSD board (Medrad Exchange price)	053-108	\$	1,462.11
PDCI board	053-111	\$	1,413.12
DRCI board	053-114	\$	480.51
PPI board (Provis, 10K series)	053-121	\$	1,488.05
Universal Head Card	053-124	\$	623.60
Head Cable, Provis 7'	054-201	\$	1,350.13
Potentiometer, Provis, Plunger	050-126-1-A	\$	652.50
Potentiometer, Provis, Mechanical Stop	050-131-1-A	\$	503.25
Microswitch, Mechanical Stop	050-176-1	\$	40.04
Screw, Captive, Provis Ped door, side	051-170	\$	19.90
Screw, Captive, Provis Ped door, rear	051-171	\$	17.77
O-ring, Provis Ped door, rear captive screw	040-123-1	\$	1.86
End cap, Provis Pedestal, Atriculating arm	051-176	\$	57.75
Screw, Provis Pedestal, Atriculating arm end cap	051-177-1	\$	2.63
Nut, Provis Pedestal, Atriculating arm end cap	051-178-1	\$	1.54
Cable, Provis, Start, Coiled	054-204	\$	540.10
PSI Jacket Hex Ring 150mL	056-221	\$	56.35

### Spectris Service Parts Kit

Drive Gear, Spectris	070-101	\$	62.39
C-clip, Drive Gear, Assy	070-106	\$	19.87
Potentiometer Kit, Spectris	070-108	\$	1,171.50
Cover, Spectris, Head, Bottom	070-110	\$	240.80
Cover, Spectris, Head, Top	070-111	\$	339.00
Decal, Spectris, Top head cover	080-108	\$	18.37
Screw, non-ferrous, 8-32 x 3/4"	071-113	\$	7.50
Screw, non-ferrous, 8-32 x 5/8"	071-114	\$	7.50
Screw, non-ferrous, 6-32 x 1/2"	071-115	\$	7.50
Screw, non-ferrous, 8-32 x 1-1/2"	071-116	\$	7.50
Thumbscrew, Remote cable	071-117-1	\$	4.88

\* Prices are subject to change without notice



# Injector Support and Service

## Common/Frequent Failure items

### Illumena Service Parts Kit

Heater, Illumena	110-107	\$	1,320.00
Potentiometer, Illumena, Plunger	120-113-1?	\$	620.55
Cover, Illumena, Head, Top	110-129	\$	167.47
Cable, Illumena, Start, Coiled	114-104	\$	748.00
Cable, Illumena, Head, 6'	114-113	\$	3,648.70
Door hinge pin, Illumena	116-102-U-1	\$	75.00
Door sleeve bearing, Illumena	116-103	\$	27.71

### CT9000 Service Parts Kit

Heater, CT9000, 200mL	120-110	\$	1,072.50
Potentiometer, CT9000, Plunger	120-113-1	\$	839.66
Ground Strap, CT9000, Head	120-129	\$	216.83
Cable, CT9000, Head, 5'	124-101-1	\$	154.68
Cable, CT9000, Head, 100'	124-105	\$	1,127.50
Cam assembly, CT9000, 125ml	126-103	\$	106.30
Cam assembly, CT9000, 200mL	126-122	\$	369.60

\* Prices are subject to change without notice